

SC-CA04 CAUTION

- (1) Observe the caution to prevent injury when handling the cold side adapter. It has many sharp edges.
- (2) Tighten the screw with proper force(0.2~0.5N·m). Do not tighten the screw with excess force. It may cause reduction of the performance or failure of the FPSC. The cold side of the FPSC is made of thin stainless steel sheet and has precision structure.
Please use thermal conductive glue to install the Cold Side Adapter.

- (1)コールドサイドアダプターには角の部分がたくさんありますので、お取り扱いの際にはけがをされないようご注意ください。
- (2)六角穴付ボルトは適正な締付け力(0.2~0.5N·m)で締めてください。FPSCの吸熱部は薄いステンレス板で形成されており、内部は精密な構造になっています。ボルトを強く締め過ぎると性能の低下や故障の原因となります。
熱伝導性接着剤を併用して取付けてください。